

Collection

Shower rail

# SH109

Article

Description

Shower rail three jets SUMO





Dimensions

Cartridge	Threaded fitting		
-	G1/2" female		
Aerator	Flow Rate (+/-10%)		
	1 BAR 7.7 l\m	2 BAR 11 l\m	3 BAR 13.6 l\m
Deschustion	Motorial		
Production	Material		

#### Main body is a single hot stamped pieces


BRASS According to CuZn39Pb3 (CW614N) Max Lead content: 2.5%

**P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it





Parts list			
ELEM.	CODE	DESCRIPTION	QTÀ
1	AQ0015203	Rail shower 900 mm	1
2	AQ0010066	Chromalux hose L150	1
3	AQ0015211	Hand shower sumo three jets	1



**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it

🖸 f 🖗





# WARRANTY

All IB Rubinetterie SpA products are warrented for 10 years from the date of purchase, for the following cases:

- Defects of casting, porosity and chrome plating.
- Operating defects caused by incorrect fabrication.

The warranty provides for repair or replacement of products with fabrication defects recognized by our technical office. There is no other type of compensation anche the merchandise must be returned FOB our werehouse. The warranty only cover surface defects (scartches, dings, etc.) on fitting that have not been installed and used, returned in its original packaging with all components. O-ring, gasket seals and components subject to wear proportional to use are warranted for 2 years.

## The warranty is void in the following cases:

Error installing and putting the product into service.

Deterioration of finisched surfaces due to use of cleaning products containing acids or abrasive substances. Deterioration of surface with finishes other than chrome plating. Their durability is, in fact, dependent on the user's care and gentleness of use.

Deterioration of the fitting due incorrect installation.

Improper repairs and maintenance performed without the company's prior authorization.

The warranty from IB Rubinetterie SpA is not renewable.

## Cleaning

We recommanded cleaning the finish surfaces with water and soap, using a soft cloth. Do not use detergents that cointain hydrochloric acid or abrasive substances.



**IB RUBINETTERIE** s.p.a via dei Pianotti 3/5 25068 Sarezzo (BS) - Italy - **T.** +39 030 802101 **F.** +39 030 803097 info@weareib.it **P.IVA** 01785230986 capitale sociale €420.000,00 i.v. www.weareib.it



